

SHEET METAL-PLUMBING AND HEATING

1. Employees working with sheet metal equipment will be properly trained.
2. Wear proper protective equipment.
3. Adequate ventilation shall be provided when working in confined spaces.
4. Points of operation, gears, and pulleys of equipment shall be guarded or shielded.
5. When working from heights above 6 feet, fall protection shall be worn.
6. Scaffolds, ladders or elevated platform's equipment shall be in good condition.
7. Material will be stacked.
8. When working on new construction, floor openings, stairwells, and open sides of buildings, guards or rails will be provided.
9. After cutting sheet metal, excessive turnings shall be cleaned up.
10. When working with cement, solvent, resin, or oil, wear proper protection.

Date